

## Technical Tip

### Handling of Lead Solutions

Prepare and store LEAD SOLUTION in plastics rather than glass containers. Avoid breathing on sections during LEAD staining in order to maintain a CO<sub>2</sub> -free environment. REASON: Pb + CO<sub>2</sub> in the presence of Oxygen forms PbCO<sub>3</sub> a white precipitate.